
HANSER



Sample Pages

Plastics Injection Molding

José R. Lerma Valero

ISBN (Book): 978-1-56990-689-7

ISBN (E-Book): 978-1-56990-690-3

For further information and order see

www.hanserpublications.com (in the Americas)

www.hanser-fachbuch.de (outside the Americas)

© Carl Hanser Verlag, München

Preface

This manual has been created thinking of plastics injection molding technicians as well as processing engineers and quality and design engineers.

The book was initially born as a small procedure guide for the company where I was working, for fine-tuning injection machines with the aim of creating a logical, safe, and optimized start-up method. Gradually, it grew and accumulated interesting information for the technicians, in my opinion, and it took shape until the final editing.

It was created for those who have ever needed a book to help and support them to understand the technology, materials, and thermoplastics injection process.

It is a book that helps identify the key points of the process and show, explore, and teach new tools to define more stable, robust, and consistent processes; a book with information, for example, such as the following:

- Clear explanations about the main key points of the thermoplastics injection molding process
- Glossaries with detailed explanations and easy-to-handle data tables
- Explanations about thermoplastics and their properties and behavior
- Support information to select material according to its further application
- Support information to determine the most suitable machine to use
- Real case examples, problems, analysis, and solutions
- Scientific injection molding explanations of tools, calculations, and portability
- Examples of defects and failures, their causes and possible solutions
- Easy and clear explanations for injection process optimization
- General processing recommendations

I hope that this book can be a tool for consulting and support during the professional life of the reader.


I also aim to encourage technicians toward a cultural change in both the analysis of problems and the parameterization and definition of robust plastics injection molding processes, where the transition from the empirical method toward the scientific method can be made using appropriate methodologies.

José R. Lerma Valero September 2019

About the Author

José R. Lerma Valero was born in Barcelona, Catalonia, in 1962; he is married and has a son. He obtained a superior degree in mechanics, with specialty in molds, and studied business management. He started his professional life as a trainee in a small injection molding factory.

José R. Lerma has dedicated close to 40 years of his professional life to the world of thermoplastics. Most of this professional life in plastics injection factories has been dedicated to producing parts for the automotive sector, producing both technical and aesthetic parts, painted, with chrome plating, etc. The functions and responsibilities he carried out in these injection plants have been of all kinds; for example, Processing Engineer, Technical Department Manager, Maintenance Manager, Production Manager, and Plant Manager.



José R. Lerma has been collaborating for more than 15 years with different technical centers in Spain as a leader of different seminars all related to plastics and the transformation of plastics, having trained hundreds of technicians in this technology.

In 2013 he published the book "Advanced Manual of Thermoplastics Transformation" in the Spanish language, with great success among plastics injection technicians.

It should also be noted that for six years he has developed and taught a specific seminar about scientific injection molding methodology in Spain, Portugal, and some Latin-American countries quite successfully.

All this accumulated background of experience in real day-to-day cases in factories as well as the training received and the experience of providing training in seminars to technicians is reflected and shared in this book.



Contents

Ack	nowledg	gments	V	
Pref	ace		VII	
Abo	ut the A	uthor	IX	
Part	1: Plas	tics		
Poly	mers		3	CHAPTER 1
1.1	Plastics	5	3	
1.2	Molecu	lar Bonds	4	
1.3	Functio	nality	6	
1.4		rization	6	
	1.4.1	Polycondensation	6	
	1.4.2	Polyaddition	6	
1.5	Determ	ination of the Molecular Weight of Polymers	7	
1.6	Thermo	oplastics	8	
	1.6.1	Classification of Thermoplastics	8	
		1.6.1.1 According to Their Molecular Structure:		
		Morphology	8	
		1.6.1.2 According to Their Molecular Chain Form	11	
		1.6.1.3 According to the Position of Atoms in the Chain	12	
1.7	•	ties and Characteristics of Plastics	13	
	1.7.1	Thermal and Physical Behavior	13	
		1.7.1.1Rheology	13 13	
		1.7.1.3 Viscosity	13	
		1.7.1.4 Glass Transition Temperature (T_g)	15	
		1.7.1.5 Melting Temperature $(T_{\rm m})$	16	
		1.7.1.6 Thermoplastics Behavior	17	
		1.7.1.7 Changes of State in Amorphous Materials	17	
		1.7.1.8 Changes of State in Semi-crystalline Materials	18	
		1.7.1.9 Behavior under Load	19	
1.8	A Brief	History of Plastics	21	
	1.8.1	1900-1930	22	
	1.8.2	1950s	23	
	1.8.3	1960s	24	
The	rmodyna	amic Behavior of Plastics: PVT Graphs	25	CHAPTER 2
2.1	Thermo	odynamics	25	
2.2	PVT Gr 2.2.1	aphs	25	
		Materials	25	

		2	.2.1.1	Dosage Stage, Plastification, Melting
		2	.2.1.2	Injection Stage, Filling the Mold or Cavities
		2	.2.1.3	Hold Pressure Stage
		2	.2.1.4	Cooling Stage
		2	.2.1.5	Influence of Injection Molding Parameters
				Reflected in PVT Graphs
		2	.2.1.6	Crystallization Stages
CHAPTER 3	Burı	n Test		
	3.1			arious Types of Plastics
	3.2			dentification of Plastics by Burn Test
OUADTED 4				. Dies 1, 5 : 1 : 1
CHAPTER 4				a Difficult Friendship
	4.1	Exposure o	n Duty	
	4.2	Water and	Polyme	er in Molten State
	4.3	Water-Sens	sitive Pl	astics
CHARTER E	A		.	District Deinforced District
CHAPTER 5		_		Plastics, Reinforced Plastics,
	and	Rubbers .		
CHAPTER 6	Gen	eral Featui	es of	Some of the Most Used Thermoplastics
	6.1	Polyolefins		
		6.1.1 P	olyethy	rlene (PE)
		6	.1.1.1	High Density Polyethylene (HDPE)
		6	.1.1.2	Low Density Polyethylene (LDPE)
		6	.1.1.3	Linear Low Density Polyethylene (LLDPE)
		6	.1.1.4	Comparison of Different Structures of
				Polyethylenes
		6.1.2 F	olyprop	oylene (PP)
		6	.1.2.1	PP Homopolymer Properties
		6	.1.2.2	PP Copolymers
		6.1.3 E	thylene	e Vinyl Acetate (EVA)
		6.1.4 E	Ethylene	e Vinyl Alcohol (EVOH)
	6.2	Polyoxyme	thylene	e (POM)
	6.3		-	•••••
				ral Purpose
				or High Impact PS (HIPS)
	6.4			diene Styrene (ABS)
	6.5			
	6.6	-	-	rile (SAN)
	6.7			ene Acrylic Rubber (ASA)
	6.8	•	` ′	
	6.9	-		
				vlene Terephthalate (PBT)
		6.9.2 F	orvethy	lene Terephthalate (PET)

6.10	Polyphe	nylene Oxide (PPO)	57	
6.11	Polycarl	oonate (PC)	58	
6.12	Polymet	hylmethacrylate (PMMA)	58	
6.13	Liquid (Crystal Polymer (LCP)	59	
6.14	-	ers	59	
	6.14.1	Thermoplastic Elastomer (TPE-V)	59	
	6.14.2	Elastomer Thermoplastic Vulcanized (ETPV)	60	
	6.14.3	Thermoplastic Copolymer Elastomer Ether Ester		
		(TPC ET)	60	
	6.14.4	Polyurethane (TPU)	61	
		6.14.4.1 Composition	61	
6.15	Styrene	Butadiene Copolymer (SBC)	62	
6.16	Ionome	°	63	
6.17	Polyphe	nylene Sulfide (PPS)	63	
	6.17.1	Properties	63	
	6.17.2	Features	64	
6.18	Polysulf	ones	64	
	6.18.1	Polyphenyl Sulfone (PPSU)	64	
	6.18.2	Polyethersulfone (PESU)	64	
	6.18.3	Polysulfone (PSU)	65	
Cher	nical Re	sistances	66	CHAPTER 7
7.1	Chemic	al Substances	66	
	7.1.1	Ethers	66	
	7.1.2	Alkalis	67	
	7.1.3	Esters	67	
	7.1.4	Ketones	68	
	7.1.5	Aliphatic Compounds	69	
	7.1.6	Halogenated Hydrocarbons	69	
	7.1.7	Halogenated Compounds	69	
	7.1.8	Amines	69	
	7.1.9	Other Chemicals that May Attack Plastics	70	
Addi	tives		74	CHAPTER 8
8.1	Stabilize	ers	74	
8.2	Lubrica	nts	75	
8.3	Antioxio	lants	76	
8.4	UV Prot	ection	76	
	8.4.1	Absorbents	76	
	8.4.2	HALS	76	
8.5	Plasticiz	zers	76	
8.6	Antistat	ic Compounds	77	
8.7		etardants	77	
٠.,	8.7.1	Combustion Mechanism of a Plastic	78	
		8.7.1.1 Solid Phase		

			8.7.1.2 Gaseous Phase
		8.7.2	Some Types of Flame Retardants 79
	8.8	Haloger	n-Free Flame Retardants
		8.8.1	Halogens
		8.8.2	Usual Names for Halogen-Free Materials 80
		8.8.3	Contribution of Halogens in Plastics
		8.8.4	Need for Alternatives to Halogenated Materials 80
	8.9	Foamin	g Agents
	8.10	Hydroly	rsis Stabilizers
	8.11	Slips an	d Antiblocking81
		8.11.1	Slips 81
		8.11.2	Antiblocking
	8.12	Nucleat	ing Agents81
	8.13	Compat	ibility Agents82
	8.14	Impact	Modifiers
	8.15	Fillers a	and Reinforcements
	8.16	Mineral	Additives
	8.17		tion Lubricants
	8.18		d Pigments
	8.19		patch
	8.20		tions
	0.20	8.20.1	Action Mode
		8.20.2	Addition Mode
		8.20.3	Some Products
CHAPTER 9	Test	s on Pla	stics 88
	9.1	Mechan	ical Tests
		9.1.1	Tensile Test ISO 527 1-2
		9.1.2	Flexural Test ISO 178
		9.1.3	Wear Resistance Test TABER ASTM D1044 90
		9.1.4	Hardness Tests
			9.1.4.1 Ball Pressure Hardness Test ISO 2039-1 90
			9.1.4.2 Rockwell Hardness Test ISO 2039-2 90
			9.1.4.3 Shore A and Shore D Hardness Test ISO 868 91
		9.1.5	Impact Charpy Test ISO 179 IZOD, ISO 180
			9.1.5.1 Izod Test ISO 180 92
		0.1./	9.1.5.2 Charpy Test ISO 179
		9.1.6	Scratch ASTM D3363
	0.2	9.1.7	Compression Set Test
	9.2		l Tests
		9.2.1	Definitions
		9.2.2	Vicat Test ISO 306 95 HDT ISO 75 95
		9.2.3 9.2.4	HDT ISO 75 95 Hot Ball Pressure Test 96
		9.2.4	Relative Temperature Index (RTI) Test
		,	

	9.2.6	Coefficient of Linear Thermal Expansion (CLTE) Test	97	
	9.2.7	Flammability Test UL94	97	
	9.2.8	Limited Oxygen Index (LOI) Test ISO 4589 1.2	99	
	9.2.9	Incandescent Glow Wire IEC 60695-2-13 and 2-12	100	
	9.2.10	Glow Wire Ignition Test (GWIT) IEC 60695-2-13, 2-12	101	
	9.2.11	Glow Wire Flammability Test (GWFT) IEC 60695-2-12	101	
	9.2.12	Reaction to Fire: Classification	101	
9.3		Tests	102	
	9.3.1	Dielectric Strength ASTM D149 IEC 60243-1	102	
	9.3.2	Dissipation Factor ASTM D150 IEC 60250	102	
	9.3.3	Dielectric Constant ASTM D150 IEC 60250	102	
	9.3.4	Comparative Tracking Index (CTI) IEC 60112	102	
	9.3.5	Surface Resistivity (SR) ASTM D527 IEC 6009 3	103	
	9.3.6	Volume Resistivity (VR) ASTM D527 IEC 6009 3	104	
9.4		gical Tests	104	
	9.4.1	Melt Flow Rate (MFR), MFI ISO 1133	104	
	9.4.2	MVI and MVR	105	
9.5		ring	105	
	9.5.1	XW Weather-Ometer	106	
		9.5.1.1 Accelerated Weathering	106	
	0.5.2	9.5.1.2 Tests in Natural Environments	107	
0 (9.5.2	Radiation	107	
9.6		n Transparent Materials	108	
	9.6.1	Residual Stress Measurement in Transparent Materials .	108	
	9.6.2	Method	108	
9.7		Lab System	109	
9.8		al Resistance and Stress Cracking	110	
	9.8.1	Electrical Properties	110	
		9.8.1.1 HWI: Hot Wire Ignition	110	
		9.8.1.2 HAI: High Ampere Arc Ignition	111	
		9.8.1.3 Time of Arc Resistance (TAR) ASTM D 495 9.8.1.4 HVAR: High Voltage Arc Resistance to Ignition	111	
		9.8.1.4 HVAR: High Voltage Arc Resistance to Ignition9.8.1.5 HVTR: High Voltage Arc Tracking Rate	111 111	
		9.8.1.6 CTI: Comparative Tracking Index	112	
		9.8.1.7 RTI: Relative Temperature Index	112	
Prop	erties o	of Plastics: Understanding Technical Data Sheets	113	CHAPTER 10
10.1		·	114	
10.2		ensity	115	
10.3		ates	115	
10.5	10.3.1	Melt Volume Index (MVI)	115	
	10.3.1	Melt Flow Index (MFI)	116	
10.4		Stress, Mechanical Resistance	117	
10.5		Modulus and Tensile Modulus	118	
10.6		Resistance	119	
10.7		ent of Linear Thermal Expansion (CLTE)	120	

	10.8	Vicat Sof	Stening Temperature	121
	10.9	Heat Def	lection Temperature (HDT or HDTUL)	122
	10.10	Thermal	Conductivity	123
			S	124
			Resistivity	124
			nductivity	125
			ard	125
	10.14	16HOW C	aiu	123
	Part	2: Mater	rial Selection	
CHAPTER 11	Mate	erial Sele	ection Checklist	129
	11.1		l Specifications	130
	11.2		actor Values	131
	11.2	rarget ra	ictor values	131
CHAPTER 12	Mate	erial Sele	ection	134
	Part	3: Inject	ion: Machines and Processes	
CHAPTER 13	The	Injection	Molding Machine	161
	13.1	Clamping	g Unit	161
		13.1.1	Clamping Force	162
		13.1.2	Clamping Unit Systems	162
			13.1.2.1 Mechanical Toggle Clamping System	163
			13.1.2.2 Hydraulic Piston Clamping System	163
			13.1.2.3 Hydraulic Closure System for Large Tonnages .	164
			13.1.2.4 Servoelectric Clamping: Movements Made	
			by Servomotors, Bearings, and High-Precision Screws	164
		13.1.3	Theoretical Clamping Force Required	165
	13.2			166
	13.2	13.2.1	Unit	167
		13.2.1	13.2.1.1 <i>L/D</i> Ratio	167
			13.2.1.2 Compression Ratio (<i>K</i> -Ratio)	167
			13.2.1.3 Plasticizing Capacity	167
		13.2.2	Screw	167
		13.2.3	Barrels	168
		13.2.4	Screw Mechanism	168
			13.2.4.1 Screw Feeding Zone, Initial Zone	168
			13.2.4.2 Compression Zone, Solids Conveying Zone	168
			13.2.4.3 Nitrided Screw vs Bimetal Screw	169
		13.2.5	Check Valve Non-Return Tip	170
		13.2.6	Nozzle	171
	13.3		the Right Machine?	173
		13.3.1	Factors to Consider for Choosing the Right Machine	173
		13.3.2	Clamping Force	174
		13.3.3	Residence Time of Material	175 175
		1 4 4 /1	INTECTION LIMIT NIZE	1/5

	13.3.5	Screw	176	
13.4	Hardenir	ng Treatments for Injection Unit	176	
13.5	The Pres	sure Multiplier	176	
		ers for Setting the Injection Molding Process		CHAPTER 14
14.1	•	Speed	178	
14.2		ing Situation	179	
	14.2.1	Filling Speed Rate	182	
		14.2.1.1 Very High Speeds	182 182	
		14.2.1.3 What Affects the Filling Speed?	182	
14.3	Melt Ten	perature	184	
14.4		ripheral Speed	185	
14.5		ssure	186	
14.6	14.6.1	Pressure Holding Pressure Switching Systems	187 188	
1 1 7				
14.7	O	Pressure	188	
14.8	_	Pressure Time	189	
	14.8.1 14.8.2	Cavity Pressure Drop	189 189	
14.9		nperature	190	
	_		192	
14.11	Cushion		192	
Corre	ect and (Optimized Methodology for the Process Start-up	193	CHAPTER 15
15.1	Requirer	nents: Information Required	193	
	15.1.1	Material	193	
	15.1.2	Part	193	
	15.1.3	Mold	193	
	15.1.4	Machine	193	
15.2	Possible	Previous Calculations	194	
15.3	-	Machines Tune-up	196	
	15.3.1	Motion Setting	197	
	15.3.2	Injection Machine Start-up	198 198	
	15.3.3	15.3.2.1 Injection Fine-Tuning	201	
	15.3.4	Progressive Mold Filling	202	
		15.3.4.1 Progressive Filling Pressure Graphs	203	
		15.3.4.2 Hold Pressure Stage	203	
		TT		
	15.3.5	Key Parameters of Process Control	204	
	15.3.5 15.3.6	Start-up and Fine-Tuning of Injection Machines—		
		Start-up and Fine-Tuning of Injection Machines— Interpreting Graphs	205	
		Start-up and Fine-Tuning of Injection Machines— Interpreting Graphs	205 205	
		Start-up and Fine-Tuning of Injection Machines— Interpreting Graphs	205 205 205	

	15.3.7 Effects of the Different F	Parameters 20
	15.3.7.1 Mold Tempera	ture 20
		ture 20
	15.3.7.3 Part Temperat	ure 20
	15.3.7.4 Dosage Stroke	20
	15.3.7.5 Back Pressure	20
	15.3.7.6 Injection Spee	d 20
	_	ure 20
	15.3.7.8 Material Visco	sity
CHAPTER 16	Generic Recommendations for Inj	ection Molding Conditions 20
CHAPTER 17	Mold Design Guide Recommenda	tions 21
	17.1 Metals Versus Steels for Molds .	21
	17.2 Runners	22
	17.3 Types of Gates	
	G	
	17.5 Cooling System in Cores	
	17.6 Venting	
	*	22
		Channels
	17.7 Draft Angles	
	17.8 Shrinkage	23
CHAPTER 18	Gates: Types and Recommendation	
	18.1 Fan Edge	23
	18.2 Submarine or Tunnel Gate \dots	
	18.3 Pin Point Gate	
	18.4 Tab Gate	23
	18.5 Sprue Gate or Direct Gate	
	18.6 Flash Gate	
	18.7 Outer Ring	23
	18.8 Inner Ring	23
	18.9 Overlarged Jump Gate	23
	18.10 Pin Gate	
	18.11 Most Common Injection Points .	
	18.12 Central Flow Distribution Channe	ıls 23
CHAPTER 19	Plastic Parts Design: Recommend	lations 23
	19.1 Recommendations	
		s Designs 23

		19.1.1.1 Relative Torsion Resistance vs Reference	240	
	19.1.2	19.1.1.2 Deformation at Constant Load	241 241	
	19.1.2	Tensile Stresses	241	
	19.1.3	Thickness Design	242	
		19.1.3.1 Changes in Thickness	243	
	19.1.4	19.1.3.2 Homogeneous Thicknesses	243 244	
	19.1.4	Sharp Corners and Radii	244	
	19.1.5	Influence of the Notches in the Impact Resistance Slots and Undercuts	246	
	19.1.0		240	
	19.1.7	Snap-Fit	247	
	19.1.6	Rigidity	248	
	19.1.9	Creep and Relaxation Tubular Frames, Screw Holes	249	
Inied	tion: So	me Practical Tips	250	CHAPTER 20
20.1		on of Runners and Gates Systems	250	
20.1	20.1.1	Gate Depth, Width, and Length	250	
	20.1.1	20.1.1.1 Defects Due to the Gates	251	
	20.1.2		251	
	20.1.2	Gates and Runners Design	252	
	20.1.3	Spiral Effect or Flow Distribution	253 254	
	20.1.5	Cooling	254	
	20.1.6	Purging or Cleaning of the Injection Unit	255	
	20.1.7	Venting	255	
	20.1.8	POM Foaming Test	257	
	20.1.9	Surface Tension	258	
		20.1.9.1 Contact Angle	259	
		20.1.9.2 Industrial Methods for Activating the Surface	2/0	
		or Increasing Surface Tension	260	
		tific Molding		
Scie	ntific Mo	olding or Injection by Advanced Methods	263	CHAPTER 21
21.1		ge and Training are Tools for the Future		
21.2	The Prod	Cess	263	
21.3	Some Co	oncepts Related to Scientific Molding	264	
	21.3.1	Molding Processor	264	
	21.3.2	Science	264	
	21.3.3	Intelligence	264	
21.4	Machine	Inputs vs Process Outputs	265	
21.5	New Pro	cessing Tools	267	
21.6	Advance	ed Methods—Scientific Injection Molding Tools	269	
	21.6.1	Relative Viscosity Analysis or In-Mold Rheology Test	269	
	21.6.2	Delta P: Determination Method	274	
	21.6.3	Process Window: Determination Method		
		(for Holding Injection Pressure Phase)	276	
	21.6.4	Gate Seal Study	278	

		21.6.5	Method and Analysis of Injection Pressure Losses along	200
		21 6 6	the Filling System	280
		21.6.6 21.6.7	Machine Portability	282 283
		21.6.8	Study of Shear Stress at the Gates	284
		21.6.9	Blank Templates	287
		21.0.7	21.6.9.1 Gate Seal Study, Blank Template	287
			21.6.9.2 In-Mold Rheology, Blank Template	288
CHAPTER 22			dsheets: Advanced Molding and Machine	289
		_		
	22.1	Thermo	plastic Processing by Injection—Advanced Manual	289
	Part	5: Failu	re Analysis	
CHAPTER 23	Proc		er Control, Failure Analysis	303
	23.1		Consider	303
		23.1.1	Clamping Unit	303
		23.1.2	Barrels	303
		23.1.3	Screws	303
		23.1.4	Nozzles	304
		23.1.5	Refrigeration System, Temperature Control in the Mold and the Machine	304
		23.1.6	Water Connection System in Molds	304
		23.1.7	Dryers and Dehumidifiers	305
		23.1.8	Grinders	306
		23.1.9	Hot Runner	307
		23.1.10	Thermoregulators	307
		23.1.11	Appearance Criteria	307
		23.1.12	Resin Handling	307
	23.2	Failure A	Analysis, Checks, and Optimizations	309
		23.2.1	Preliminary Investigation of Failures	309
		23.2.2	Process Optimization	310
			23.2.2.1 Radii	310
			23.2.2.2 Cold Slug	310
			23.2.2.3 Steps for Analysis of Problems Derived from	211
		22.2.2	Plastics Injection Molding Process	311
		23.2.3	Trials Injection Molding Parameters Template	314
CHAPTER 24	Typi	cal Prob	lems in Plastics Injection	315
	24.1	Lack of l	Drying or Dehumidification	315
		24.1.1	Materials Drying	316
		24.1.2	How to Properly Dehumidify	317
	24.2	_	ystem	317
		24.2.1	Effects on the Quality of the Parts	318
		24.2.2	Runners System Design	319
	24.3	Proper F	Position of the Gate	319
		24.3.1	Consequences of a Non-correct Gate Location	320

	24.3.2	Recommendations for Correct Gate Location	320	
24.4	Hold Pre	ssure Time Too Short	321	
	24.4.1	Hold Pressure Stage	321	
	24.4.2	Hold Pressure Time Too Short	321	
24.5	Inadequa	ate Melt Temperature	322	
	24.5.1	Incorrect Melt Temperature	322	
	24.5.2	Signs of Incorrect Melt Temperature	322	
	24.5.3	Correct Melt Temperature	322	
		24.5.3.1 Melt Temperature Measurement	322	
		24.5.3.2 30/30 Melt Temperature Measuring Method	323	
24.6	Correct 1	Mold Temperature	323	
	24.6.1	Incorrect Mold Temperature	324	
	24.6.2	Recommendations to Properly Adjust the Mold		
		Temperature	324	
24.7	Residues	on Mold Surface	325	
	24.7.1	Types of Deposits	325	
	24.7.2	Mold Care		
24.8	Excessiv	e Material Drying	327	
	2.1005517	0 1.20.00.10.00.00.00.00.00.00.00.00.00.00.00	327	
Defe	cts in In	jection Molded Parts	328	CHAPTER 25
25.1		n Parts Manufactured by Thermoplastics Injection		
			328	
	25.1.1	Sink Marks or Uncompensated Shrinkage	328	
	25.1.2	Streaks	330	
		25.1.2.1 Streaks Caused by Burns	330	
		25.1.2.2 Streaks Caused by Moisture	330	
		25.1.2.3 Streaks Caused by Trapped Air	331	
	25.1.3	Weld Lines	332	
	25.1.4	Grooves, Vibrations, and Corona Effects	333	
	25.1.5	Gloss	333	
	25.1.6	Jetting	334	
	25.1.7	Spots and Markings near the Gate	335	
	25.1.8	Black Spots	335	
		25.1.8.1 Process	335	
		25.1.8.2 Machine	336	
		25.1.8.3 Polymer	336	
	25.1.9	Inhomogeneous Material	336	
	25.1.10	Blushes near the Gate	337	
	25.1.11	Bubbles	337	
	25.1.12	Cracking	337	
	25.1.13	Delamination	337	
	25.1.14	Splay, Silver Marks	337	
	25.1.15	Warpage	338	
	25.1.16	Stress Cracking, ESC	338	
	25.1.17	Surface Scratching	338	
25.2		n Injection Molding and Painted Parts	338	
	25.2.1	Holes and Craters	338	

		25.2.3 Part Molded with Stress	338 339 339
			340
		9	340
		,	340341
	25.2		
	25.3		341
	25.4	g	342343
			343
			343
			344
CHAPTER 26	Analı	rain of Dool Coope	245
CHAPTER 20			345
	26.1		345
		, 0	345347
	26.2	Q,	349
	26.2		349
			350
	26.3		350
	26.4		351
	26.5		352
	26.6		355
	26.7		356
	20.7	·	356
			356
			356
			357
	- (-		357
	26.8	^^	357
	26.9		359
			360
			361
	26.12	Gloss Caused by the Glass Fiber Reinforcement	363
	26.13	Pressure-Limited Process: Always a Mistake to Avoid	365
	26.14	Streaks in Transparent Polycarbonate	367
		, 3	367
			368
			368
	0/15		368
	20.15	,	369 371

26.16	Unbalanced Runners	372	
26.17	Material Degradation	372	
26.18	TPU: The Unknown Thermoplastic	373	
	26.18.1 What is TPU?	374	
	26.18.1.1 Dehumidification	374	
	26.18.1.2 Back Pressure	375	
	26.18.1.3 Hold Pressure	375	
	26.18.1.4 Cooling and Total Time Cycle	376	
26.19	Bubbles	376	
	26.19.1 Bubbles Caused by Trapped Air	377	
	26.19.2 Bubbles Caused by Vacuum	377	
26.20	The Secret of the Night Shift Manager	378	
	26.20.1 Dryers and Dehumidifiers	379	
Part	6: Reference Material		
Refer	ence Data Tables	383	CHAPTER 27
27.1	Maximum Residence Time	383	
27.2	Usual Mold Temperatures	383	
27.3	Shrinkage	384	
27.4	Drying Conditions	384	
27.5	Maximum Allowed Humidity Data	385	
27.6	Recommended Depth Venting Channels	386	
27.7	Mold and Melt Temperatures, Shear, and Other Properties	386	
27.8	Maximum Peripheral Speeds	387	
27.9	Density, Melt at Room Temperature	388	
Biblio	ography	389	CHAPTER 28
Gloss	sary	390	CHAPTER 29
Discl	aimer	394	
Index		395	

7.1.9 Other Chemicals that May Attack Plastics

Oils



Fatty acids



Alcohols



Detergents



Acids




Environmental stress cracking (ESC) is a major cause of failures in plastics, especially amorphous plastics.

Exposure of polymers to chemicals tends to accelerate the process of cracking or crazing. This process begins with stress much lower than that needed to produce cracks simply in contact with air. The mere effect of both conditions separately, stress or contact with an aggressive chemical, need not necessarily result in ESC. This phenomenon usually occurs when a combined action of both effects occurs.

ESC depends on multiple factors such as crystallinity, surface roughness, residual stress, presence of chemical agents, temperature, and strain level or molecular stretching.

The ESC effect can be minimized by lower residual stress and molecular stretching during the injection process. The use of cold molds should be avoided, as they cause residual stresses that will accelerate the ESC. Polymers of higher molecular weight should be used, because they are more resistant to ESC.



Chemical resistances


LIMITED RESISTANCE, MINOR OR MODERATE ATTACK. USE BRIEFLY
GOOD RESISTANCE, MINOR ATTACK
EXCELLENT RESISTANCE, WITHOUT ATTACK
LOW RESISTANCE. NOT RECOMMENDED

DILUTED ACIDS
CONCENTRATED ACIDS
ALCOHOLS
ALDEHYDES
BASES
ESTERS
ALIPHATIC HYDROCARBONS
AROMATIC HYDROCARBONS
HALOGENATED HYDROCARBONS
KETONES
MINERAL OIL
VEGETAL OIL


MAX TEMPERATURE °C MIN TEMPERATURE °C


AUTOCLAVE STERILIZATION
MICROWAVES
GAS STERILIZATION
DRY HEAT STERILIZATION
GAMMA RAY STERILIZATION
CHEMICAL STERILIZATION

NITROGEN PERMEABILITY CO2 PERMEABILITY OXYGEN PERMEABILITY



Chemical resistances





9.1.2 Flexural Test ISO 178




Figure 9.1 Universal testing machine; source: Zwick-Roell

This flexural test measures the extent of bending resistance of a material and its stiffness. To carry it out, a specimen is placed so that it rests on two points. Then, pressure is applied at its midpoint.

Test speed: 2 mm per minute.

To calculate the flexural modulus, the load/deflection curve is drawn. The flexural modulus is determined by the slope of the line tangent to the stress-strain curve in the region where the plastic has not yet been permanently deformed or where elastic strain occurs.




Figure 9.2 Graph of flexural stress; source: Zwick-Roell

3,40

9.1.3 Wear Resistance Test TABER ASTM D1044



Figure 9.3 TABER machine; source: Neurtek

This wear resistance test measures the amount of material loss by abrasion or wear.

The sample is mounted on a turntable which rotates at 60 rpm. Loads are applied as weights that push the abrasive wheels against the sample. After a certain number of cycles the test is stopped.

The mass lost by abrasion is indicated in mg/1000 cycles.

9.1.4 Hardness Tests

9.1.4.1 Ball Pressure Hardness Test ISO 2039-1

A 5 mm diameter ball of hardened and polished steel is pressed at 358 N on a sample surface with a minimum thickness of 4 mm. 30 seconds after, the depth of impression is measured.

Hardness pressure is calculated by dividing the load applied by the mark area (N/mm^2).

9.1.4.2 Rockwell Hardness Test ISO 2039-2

The diameter of the ball depends on the Rockwell scale used. The indenter is made of hardened and ground steel. The sample is subjected to a lighter load. A heavier load is then applied and, finally, the lighter load is applied again.

The measurement is based on the total penetration depth achieved. The values are always between 50 and 115 (in Rockwell units).

The scale increases in severity R to M through L.

Table 9.1 Rockwell Hardness Test

Rockwell hardness scale	Lower load (N)	Higher load (N)	Ball diameter (mm)
R	98.07	588.4	12.7
L	98.07	588.4	6.35
M	90	980.7	6.35






Figure 9.4 Rockwell hardness conditions and sequence

 $\textbf{Figure 9.5} \ \ \textbf{Rockwell hardness test machine; source: Zwick-Roell}$

Rockwell hardness calculation = 130 – E (see Figure 9.4).

Units: 0.002 mm (one unit per each 0.002 mm of the mark depth).

9.1.4.3 Shore A and Shore D Hardness Test ISO 868

The Shore A test is intended for soft materials. The Shore D test is intended for harder materials.

Pressure is applied on the sample for 15 seconds. Hardness is read on the durometer scale. Values range from 0 (total penetration: 2.5 mm) to 100 (no penetration).

Shore A hardness ranges from 10 to 90. Shore D hardness ranges from 20 to 90.

Shore A values over 90 require switching to the Shore D scale. Shore D values under 20 require switching to the Shore A scale.







Figure 9.6 Shore A durometer; source: Zwick-Roell

9.1.5 Impact Charpy Test ISO 179 IZOD, ISO 180

The sample specimens are different between ISO and ASTM. See Table 9.2.

Table 9.2 Sample Dimensions for Charpy Impact Test

	Thickness	Length
ISO sample	4 mm	80 mm
ASTM sample	3 mm	60 mm

The impact Charpy test is used to estimate the degree of weakness or strength of material samples subjected to impact. We can thus compare the toughness of different materials.

The sample is placed in the specimen holder. Then, a pendulum hammer (with a hardened steel tip of a certain radius) is dropped from a certain height. The impact causes shearing of the sample material due to the sudden load.

The height difference between the baseline and the residual height reached by the hammer represents the energy absorbed by the sample.

This test can be performed at different temperatures. It can also be performed with or without notches in the sample.

9.1.5.1 Izod Test ISO 180

The result of this test is obtained by dividing the energy required to break the sample by the initial area. The result is expressed in kilojoules per square meter, kJ/m^2 .

The Injection Molding Machine



Figure 13.1 Injection molding machine; source: Wittmann-Battenfeld

The characteristics and instructions included in catalogs and technical documentation brochures provided by injection machine manufacturers allow us to determine if a machine can be technically optimal for producing a particular project or part made by an injection molding process.

The injection machine can be divided into two main units: the clamping unit and the injection unit.

The clamping unit comprises, among others, the clamping force, the moving plate stroke, the tie bar free spacing, the mold minimum and maximum thicknesses, clamping and opening mold speed, etc.

The injection unit incorporates several characteristics, like the screw diameter, maximal pressure, L/D ratio, compression ratio, plasticizing capacity, maximal injection volume, heating power, maximal injection speed, etc.

13.1 Clamping Unit



Figure 13.2 Clamping unit

Clamping unit determines:

Clamping force Mold maximum and minimum

thicknesses

Moving plate stroke Plate thickness

Tie bar free spacing Ejection stroke

13.1.1 Clamping Force

Function and characteristics

- Keeping the mold closed so it does not open due to the injection pressure thrust during the cavity filling and packing.
- When the product obtained by multiplying the projected part area in the mold by the injection pressure needed exceeds the closing force, the tie bars are overstressed and elongate even more. They can exceed the steel elastic tensile limit and break or deflect the clamping plates.
- The mechanical clamping systems are stiffer than hydraulic clamping systems.
- The hydraulic clamping system exerts pressure close to the center of the plate.
- The latest generation of mechanic toggle clamping systems also concentrate strength close to the center of the movable plate.

Movable platen stroke

A longer stroke will make the machine more versatile. In the hydraulic clamping systems, the total stroke of the piston is equal to the sum of the mold thickness and the maximum opening mold stroke.

Tie bars distance

The distance should be the widest possible, provided that the plate bending will be respected.

Stationary and movable platen

They should be parallel. The weight of the movable platen and mold must rest on the base of the bed and not on the tie bars.

Mold size regarding the platen size

According to the rule of thumb, the molds whose base area regarding the movable platen is less than ¼ of the area of the platen should not be placed.

The projected area of the molds used should not be less than a quarter of the area delimited by the tie bars in the clapping platen. If the mold area were smaller, the plates could be flexed more than recommended.

13.1.2 Clamping Unit Systems

According to their design, we can distinguish the following sealing systems:

- Mechanic toggle clamping system
- Hydraulic clamping system
- Hydraulic two-stage piston system
- Tie-barless system
- Electrical system




Figure 13.3 Toggle clamping system schema; source: Ascamm

13.1.2.1 Mechanical Toggle Clamping System



Figure 13.4 Tie-barless clamping unit detail; source: Helmut Roegele

13.1.2.2 Hydraulic Piston Clamping System




Figure 13.5 Hydraulic clamping system; source: Ascamm

There are several kinds of two-stage clamping systems that may be included within the hydraulic clamping systems. The most common system is a mechanical lock in the machine made by two very small hydraulic cylinders, driving two locking parts which act over the central axis. Once the central axis is locked, the high pressure enters through a larger cylinder (pressure cylinder), moving it only a few millimeters, to provide the necessary and programmed clamping force.

13.1.2.3 Hydraulic Closure System for Large Tonnages




Figure 13.6 Hydraulic clamping system scheme; source: Ascamm

There are as many hydraulic clamping systems as there are machine manufacturers. All of them have tried to develop more versatile, fast, accurate, and low-maintenance systems.

In general, these devices have a system of small-section and low-volume piston to effect a fast closing movement. Thus, this movement requires little volume of oil and, therefore, has a low energy cost and is performed very rapidly. The system is complemented with a large piston. This piston performs the final locking of clamping force by a short stroke.

13.1.2.4 Servoelectric Clamping: Movements Made by Servomotors, Bearings, and High-Precision Screws







Figure 13.7 Servoelectric motor clamping


Generic Recommendations for Injection Molding Conditions


Attention: follow carefully the recommendations in this chapter. The author assumes no responsibility for incidents, accidents, damage to equipment or people, or adverse outcomes that may occur.














25.1.2 Streaks

25.1.2.1 Streaks Caused by Burns





This thermal degradation is caused by excessive temperatures and/or residence times; gases are generated by the decomposition of the polymer or additive pack. Brown or silver streaks can be seen in the workpiece surface.

When the molecular structure is thermally degraded, the molecular chain can decrease, and silver streaks appear. The change in the macromolecules causes a brownish discoloration.

The heat required for thermal degradation of the material may come from the injection unit setting, from an excessive shear during dosing (back pressure) by a high peripheral speed (rpm), from an excessive shear on sharp edges, from sudden changes of direction, etc.

Verifications-To Check:

- Check if the melt temperature is near the upper limit recommended or even above.
- See if the streak appears behind narrow sections of passage of material.
- Check if the defect can be reduced by decreasing the injection speed.
- Check if the reduction in the melt temperature has a positive effect on the defect.
- Check if the degradation streak is affected by a high residence time caused by interruptions, excessive cycle, or inadequate machine size.
- Check for a considerable amount of regrind material or dust from the regrind process.
- Check there are no retentions inside the hot runners.
- Check that the nozzle is working properly and there are no retentions. Pay attention to shut-off hydraulic nozzles.
- Check that time and temperature of pre-drying material are not excessively high.
- Check that the shear originated during the dosing by screw rotation is not excessive (keep within the recommended limits for the material).

25.1.2.2 Streaks Caused by Moisture

They appear on the part surface with the shape of comet trails. The surface surrounding the silver streaks is porous and rough. This can be seen under a microscope.








Figure 25.4 Melt flow and gas bubles during the cavity filling; source: Ascamm

Residual humidity in the melt causes gas evaporation of water inside. These gas bubbles tend to come out to the surface by the advancing flow effect from inside to outside. Trapped bubbles burst at the surface with the application of pressure, creating the visible effect of the streak.

Verifications-To Check:

- Hygroscopic materials such as PA, PBT, ABS, PC, PMMA, TPU, and others need a thorough pre-processing dehumidification. Check the polymer manufacturer's recommendations.
- When material is ejected, the purge bubbles may appear and release steam if the material is not sufficiently dehumidified (inconsistency of purging).
- The flow front has crater-like structures.

25.1.2.3 Streaks Caused by Trapped Air





Figure 25.5 Examples of streaks caused by trapped air; source: Ascamm

They appear as matte, silver, or white streaks near the last filling zone. They also appear in areas with ribs, thickness variations, letters, reliefs, etc. The air concentrated in the ribs and grooves can be surpassed by the flow front and be trapped in the melt.

The air unable to escape during filling goes to the surface and becomes compressed in the direction of flow during the hold pressure stage.





Verifications-To Check:

- Make sure that the suction is not the cause of the problem.
- Perform tests decreasing the injection speed to minimize the problem.
- See if ejection purge shows bubbles or explosions and if the flow front has craters.
- Verify the back pressure. If the back pressure is low, the air is not completely removed from the pellets during dosing.
- Verify possible wear in the screw barrel of the plasticizing unit.

25.1.3 Weld Lines

When several flow fronts face each other, the flow front edges that are rounded come in contact and are crushed against each other. If temperature and pressure are not high enough, the corners in contact with the cavity will not bind on the entire surface and microcracks appear. Fluids do not mix homogeneously. At this time it is very important that the aeration or venting of the mold has been effective.












Figure 25.7 Weld lines between two flow fronts can cause air entrapments

Verifications-To Check:

The flow fronts must coincide quickly and with a higher temperature to reduce the incidence of the defect. To achieve this, the following conditions could be tested and checked:

- Material with higher melt flow
- Increased mold temperature
- Increased melt temperature
- Increased injection speed
- Proper venting in critical areas
- Increased hold pressure
- Gates dimensions
- Gates location

Sometimes, we can adapt overflow areas in the welding lines position to promote that the weld line be placed out of the critical zone of the part. However, we must re-work and cut this area later.

25.1.4 Grooves, Vibrations, and Corona Effects

Very fine grooves formed by concentric rings, like those of a vinyl record, can be seen on the surface of the part. Their appearance is due to the formation of a solid layer behind the flow front, which is cooled very rapidly. The cooling of the peripheral layer also causes cooling of part of the flow front. When this happens, a new layer from the melt flow passes through the cold flow front, creating a new groove or line.







Verifications-To Check:


These actions help to increase the speed of advance of the flow:

- Increase the injection speed
- Increase the maximum injection pressure (no limited process)
- Increase the melt temperature
- Avoid small gates and channels
- Use materials with less viscosity (more fluid)

25.1.5 Gloss










Figure 25.9 Left: high gloss, light reflection, narrow intensity distribution; right: low gloss, light reflection, broad intensity distribution

The brightness of a part is due to the refraction of light on its surface. Gloss differences are due to the different behavior of this surface, caused by various reasons (differences in mold surface, shrinkage differences, cooling differences, different mold temperature, inner vacuoles, orientation of pigments, fillers, etc.).

Verifications—To Check:


- Check the mold temperature (a high temperature causes parts with higher gloss)
- Check the melt temperature (a high temperature causes parts with higher gloss)
- Injection speed: a high injection speed usually increases the part's surface gloss
- Cavity mold surface texturing
- Design of ejection system
- Radiate sharp corners
- Design with uniform thickness
- Provide operational venting channels
- Take into account the different temperatures in molds, runners, ejectors, etc.; these thermal gradients generate differences in surface gloss

25.1.6 Jetting



Jetting is a free melted material jet forcing the melt to zigzag within the cavity. When the melt touches the walls of the mold, it is cooled and cannot melt homogeneously with the rest of material that goes into the cavity.

Figure 25.10 Correct and incorrect gate position; it can cause jetting in the molded part



Verifications—To Check:

- Reduce first injection speed to pass through the gate
- Increase melted mass temperature

Advice:

- Use lubricant grease or oils that are compatible with the polymer used
- Manufacture molded parts without stress. With this purpose:
 - Use the adequate melt temperature as recommended by the manufacturer
 - Minimize residence time of the material in the injection unit
 - Dry the material properly

26.2.2 Material Selection

If the stresses exceed the strength of ABS, it shall be broken without remedy. If it is possible to know the stresses applied, we can find a material that brings us a safety margin during its use.

In summary	
Problem	Broken parts during use
	Material: ABS
Causes	Stress cracking
	No radii
	Polymer degradation
Advice	Replace chemicals
	Apply radii
	Change melt and dry temperatures

26.3 Broken Gears







The absence of radii, a careless dehumidifying, and the low crystallinity of the material obtained in injected parts causes brittle fractures under stress during use.

I received several parts with visible breaks. I started watching the pieces for possible problems. They were mechanical parts used in gears, with a central housing for a square shaft. I applied a flame to try to identify the type of material and I got a strong scent: it smelled similar to a "burning horn". When the piece burned, it formed dripping threads. It was made of polyamide (PA).

I also noted bursts and microbubbles in the surface of most parts received. Some had pores or vacuoles in the section break. I also saw the remains of a direct gate. All pieces had a very pronounced weld line in front of the gate.

Possible Causes of Brittleness

The samples indicate that the dehumidifying was not enough. There are traces of humidity everywhere.

The central core, squared, is not radiated on the front side, where it meets the bottom wall of the piece. This generates shear and accumulation of stresses. I

passed the pen on the radii and could clearly see a double line, indicating the absence of radius.

I observed two types of gate: a submarine and other direct by piece. If both work separately and individually, they are not sufficient to fill and package the part.

Advice:

- Dry the raw material (in this case PA) at 80 °C for 12 hours.
- Increase the mold temperature for maximum crystallinity of the polymer (80 °C would be suitable). This would provide more and better mechanical properties.
- Humidify or condition the parts and prepare them before including them in the assembly step. PA parts have to be conditioned to reach their equilibrium of humidity absorption, to achieve the properties of use.
- Radiate cores in the central square of the base, where it meets the wall of the part.
- Increase direct gate in order to compensate the shrinkage that promotes the internal vacuoles.

In summary	
Problem	Broken parts during use
	Material: PA
Causes	Mold temperature
	No radii
	Irregular drying
	Gate with incorrect dimensions
Advice	Increase mold temperature
	Apply radii
	Correct and proper material drying
	Increase the gate dimension



26.4 Unfilled PC Cover



Improper thickness of the wall connected to the gate prevents the proper filling of the transparent PC sheet.

In this case, the problem was in a transparent cover made of polycarbonate (PC). The filling of the cavity was hard and flow lines and corona effect (see Chapter 15) were seen in areas far away from the gate.

After cutting the piece, I noticed that the wall where the gate is located (this is in the center of the part) was too thin (1 mm) in relation to the perimeter side walls (4 mm), rather thick.

The "thick to thin" rule is not observed in this case. Neither has been included a semi-spherical facilitator flow in front of the gate. This simple mechanization



facilitates filling, especially at first, and minimizes friction and shear near the gate.

The gate is too small for the volume and section of the part. If we double the gate section, we quadruple the volume that can pass through it.

It is recommended that the wall connected to the gate should be the thinner wall of the part. Flow restriction prevents the filling and holding pressure of the cavity in the thicker areas.

Advice:

- Review design to increase the thickness of the wall connected to the gate
- Warm the mold (PC can be worked at 90–100 °C)
- Have a facilitator flow in front of the gate
- Increase the gate section for easy filling and packing of the cavity
- Use a more fluid PC



In summary	
Problem	Incomplete parts
	Material: polycarbonate
Causes	Wall design with incorrect gate
	No flow facilitator in front of gate
	Gate with inadequate dimensions
Advice	Increase mold temperature
	Mechanize facilitator for easy filling
	Increase the gate section
	Use more fluid material

26.5 Dimensional Instability in Parts





Cavity filling imbalances cause unacceptable dimensions differences in the parts.

In this case, the difficulties encountered to manufacture consistent dimensions in precision parts make it impossible to carry out the work.

During fabrication of a colored transparent polystyrene (PS) ring, the degree of dispersion of the dimension obtained exceeds the specified tolerance for this product. The tolerances for these products are very low and cannot stabilize the dimensions variation range.

After a meeting with the customer, I visited the injection plant to observe the full injection process. The three plates mold has eight cavities. Such a high number of cavities is not recommended when one wants to make very high precision parts.

I decided to measure the parts and analyze the cavity number groups. I saw a significant spread between the parts obtained from different cavities number.

At this point I wondered:

- Is the switching point correct?
- On many occasions this point is not properly programmed, causing:
- 1. Overcompaction
- 2. Partial filling of the part during the hold pressure stage, without speed control
- Is the injection pressure limit being reached?
 Often, the filling is limited by the injection pressure limit and we have no control of the speed of filling the cavity.
- Does the flow front advance uniformly?

Normally, injection speed profile curves are set flat or with a constant injection volume during all the filling stroke. This causes the flow to accelerate or decelerate according to the sections of passage of the material, runners, etc. We do not control the flow front speed.

■ Is the hold pressure time right?

Normally, this time is set depending on the weight (there are two limits) or depending on the part (dimensions, flashes, grips, etc.), or when the part fails to gain weight. We should not make perfect runners by increasing hold pressure time, cycle, or energy expenditure.

Do we want to switch to hold pressure stage by hydraulic pressure?
 Normally, this system is not too used although it is the most reliable (outside

the cavity pressure switching) and is available in almost all current standard machines. We must make better use of available technology in factories.

We make a start from zero, following these steps:

Injection Pressure Limit

Set the pressure value above the real pressure needed to ensure that we do not limit the injection process. There is nothing worse than a pressure-limited process.

Holding Pressure

Set the hold pressure time and hold pressure to zero.

Switching Stroke

Set the switching point close to the dosage point in order to inject a little injection volume in the cavity. We want to fill only a small amount of the part.

With these premises, we can start the progressive filling of the cavities.

During filling, we modify the switching point position to inject a greater quantity of material in each cycle. Suddenly, we find that certain cavities are completely filled while others are not. The eight cavities have not been filled in a balanced way. The probable cause is the small differences in gates and/or runners channels, in addition to the "spiral" effect. Here we identify a cause of the spread of dimensions between cavities.

We cannot obtain narrow dimensional tolerances in an unbalanced mold during filling.

After obtaining the correct switching point position, we proceed to pressurize and pack the cavities. We use the gate seal analysis. First we select a hold pressure time excessively overrun, which ensures that the gate will be closed or sealed and a low hold pressure level.

We increase the pressure values until the pieces are aesthetically and dimensionally correct. At this point we have an excessive holding pressure time, which ensures the gate seal. Then we weigh the injected parts without runner and we gradually reduce the holding pressure time, controlling the weight of each shot.

There will come a moment when the weight will decline. This indicates that the gate was not sealed. So we increase in the previous the step holding pressure time, 1 second or so, and ensure the sealed gate with the shortest hold pressure time possible and, therefore, the optimum time.

Finally, we decrease the pressure injection limit to a value slightly above the necessary real filling pressure. In this way we ensure that it does not interfere with normal filling cavities, and it becomes a security element to any clogged or closed cavity.

With these steps, the dimensions of injected parts are dimensionally repetitive and consistent and will be dimensionally stable although the cavities filled first are bigger. To eliminate this last problem we have to ensure that the dimensions of channels and gates are identical.




Hold pressure

Key points:

- 1. Do we work with a sealed gate or with an open gate?
- 2. How much time will be set in hold pressure stage?
- 3. How much hold pressure will be set?

Points 1 and 2 determine if we work with sealed or open gates.

- 1. Place a hold pressure time much longer than necessary to seal the entrance
- 2. Start with a low hold pressure and gradually increase until the piece is OK. This pressure is to study the sealing time of the gate. It is not the pressure with which we will work
 - 3. Weigh the part
- 4. Gradually reduce hold pressure time and weigh the part until we have 0.5 seconds holding pressure
 - 5. Reflect times and weights on a chart



Sealed gate processes are better and more stable.

Advice:

- Match and balance filling between cavities; adjust gates and channels if necessary
- Change the injection process for an optimum hold pressure time with sealed gate
- Adjust any cavity if it is outside the tolerance range


In summary	
Problem	Process with little robust dimensions
	Dimensional instability
Causes	Cavity unbalanced
	Unoptimized hold pressure
Advice	Balance filling between cavities
	Set post-pressure correctly
	Work with sealed gate

26.6 Insufficient Filling



A change in the polymer used may hinder the filling of the cavity.

In this case, the part was made with a blend of PC-ABS. This blend is a material of high/medium viscosity. The flow path respect to the average thickness of the part was quite unfavorable. The average thickness of the part was 2.5 mm.



In this case there had been a change of material. Previously, the material filled perfectly with this mold. The filling problems began when it was replaced by the new blend.

Given the large difference in viscosity between the two materials, it was necessary to review and modify certain aspects of the mold to properly fill the cavity.

Although the value of the MFI in each case is important, it can lead to certain errors. For example, if we look at a PP and a PC with a melt index of 4 g/10 m, this does not mean that we can fill the same cavity with both materials. In the case of PP, its viscosity may decline by a factor of 100 because of the shear rate, and, in the case of PC, the viscosity can be reduced by only a factor of 5.

Advice:

- Modify distribution channel, increasing the section
- Increase the section of the runner and submarine gate
- Increase the gate section
- Increase real walls section connected to the gate





Index

Symbols

30/30 melt temperature measuring method 323

Α

absorption of water 37 ABS part 359 accelerated weathering test 106 acronyms 41 acrylonitrile butadiene styrene (ABS) acrylonitrile styrene acrylic rubber (ASA) 54 additives 6,74 adhesion 344 advanced technician 265 aesthetic aspect 363 aesthetic defects 284, 362 aesthetic limitations checklist 130 aliphatic compounds 69 alkalis 67 allowed humidity 385 amines 69 amorphous 8 antiblocking additive 81 antifriction lubricants 84 antioxidant additive 74, 76 antistatic compounds 77 application environment, requirements checklist 129 atactic 12 atmospheric plasma treatment 260 axially symmetrical parts 320

В

back pressure 30, 186, 198, 207, 332, 337, 368, 375 back pressure recommendations 209 bactericide additive 87 bacteriostatic additive 87 Bakelite 23

balanced distribution channel 220 balanced filling system 370 ball pressure hardness test 90 ball valve 170 barrels 303 barrier screws 303 beryllium copper 218 bifunctional 6 bimetallic effect 360 bimetallic hard treatment 168 birefringence in transparent polymers 108 black spots 336 blend ABS-PC 53 blisters 343 block copolymer 374 blushes near the gate 337 bonding of materials 157 breaks 357 break stress 118 brittle fractures 350 brownish discoloration 330 bubbles 337, 343, 376 bubbles and peaks 343 bulk density 115 burns 330 burn test 35 butadiene particles size 343

C

calculation

- estimated clamping force 165
- intensification ratio 289
- portability of process 289
- process analysis and optimization
- residence time in the injection unit
- scientific injection molding tools
- shear in rectangular gates 289
- shear in round gates 289
- turbulent flow (NR) 289

carbon 4

cavities balancing study 283, 284, cavity filling 31, 181 cavity filling imbalances 352 cavity mold surface texturing 334 cavity pressure 206 central flow distribution channels 238 Charpy test 92 check valve non-return tip 170 chemical resistances 66 clamping force 162, 194 clamping unit 161 clamping unit systems 162 CLTE test 97 coefficient of linear thermal expansion (CLTE) 120 cold layer 182 cold runner 252 cold slug 229, 310 collodion 22 comparative tracking index CTI 136 comparative tracking index test 112 compatibility agents 82 compensation of the volumetric shrinkage 347 compression ratio 167, 303 compression set test 94 compression zone 167 concentric circular, dark area around the gate 356 contact angle 259 conversion systems 282 cooling 30, 254, 376 cooling part 29 cooling speed 190 cooling stage 27 cooling system in cores 226 cooling time 195, 279 cool skin 280 copolymer 12 copolymer POM 50 corona 341 corona effect 333, 351

corona treatment 260

correct cavity balance 284 cost requirements checklist 130 covalent bonds 4 cracking 337 cracking of polymers 66 cracks 329, 339 crawling 340 craze 329, 349 crazing of polymers 66 creep 19, 248 creep modulus 21 cross cut test 341 cross-links 11 crystallization of polymers 33 CTI test 102 cushion 192

D

cycle time 190

defects 343 defects due to the gates 251 defects in chrome plating on plastic parts 342 deformation at constant load 241 degradation of polycarbonate 336 degree of polymerization 3 delamination 337 delta P 266, 274 delta P study 289 demolding taper 376 density 114 deposits in the mold, cause 325 deposits, recommendations to prevent 326 depth of the gate 337 deviations 263 deviations between cavities 284 dew point 317 diagram molding 277 diagram of molding area 278 dielectric constant test 102 dielectric strength 137 dielectric strength test 102 diesel effect 198, 347 differential shrinkage 359, 361 dimensional instability in parts 352 direct gate 234 dispersion 85

dissipation factor test 102 distribution channel 372 dosage 192 dosage and metering zone 168 dosage calculation 289 dosage stage 26 dosage stroke 195, 207 double bonds 4 draft angles 230, 357 drooling material 197 drop injection pressure study 289 dryers 379 dryers and dehumidifiers 305 drying of material 345 drying system 379 dull spots 363 dyes and pigments 84

Ε

ejection stress 357 ejectors 375 ejector stroke 201 ejector venting design 256 elastomers 11, 59 elastomer thermoplastic vulcanized (ETPV) 60 empirical method 264 environmental stress cracking (ESC) 70.349 equivalences between different steels 219 esters 67 ethers 66 ethylene vinyl acetate (EVA) 50 ethylene vinyl alcohol (EVOH) 50 excessive material drying 327

F

failure analysis 303
fan edge 231
fiber orientation 371
fibers 82
filling in a balanced way 353
filling pressure 30
filling pressure at switch point 266
filling speed rate 182
filling system 317

filling system review and optimization 347 filling time 202, 265, 274 flame retardants 77 flaming 341 flashes 272, 277, 303, 315, 363 flash gate 234 flat nozzle 172 flexural modulus 89 flexural test ISO 178 89 flow front 353 flow restriction 352, 358 foaming agents 81 forced air heaters 345 functional group 6 functionality 6

G

gas bubbles 331 gate 318, 368, 371 gate depth 250, 348 gate, frozen 279 gate length 348 gate position 225, 319 gates and runners design 252 gates design 224 gate seal analysis 267, 354 gate seal study 278, 287, 289 gate seal study curve 279 gate section 335, 368 gates, most common 224 gates recommendations 209 gate too small 352 gate types 231 gate width 348 gate width and length 250 generic recommendations 209 glass microspheres 82 glass transition temperature 15, 94 gloss 333, 363 graining and peaks 363 grinders 306 grooves 333 gutta-percha 22 GWFT test 101 GWIT test 101

Н

halogenated compounds 69 halogen-free flame retardants 79 halogens 79 HALS 75, 76 haze 155 HDT 138 HDT. DTUL 95 heat conductivity 125 heat deflection temperature 122 hesitation effect 361 heterodisperse 7 high ampere arc ignition test 111 high density polyethylene 46 high gloss 333 high-performance polymers 149 high residence time 330 high shear 344 high voltage arc resistance to ignition test 111 high voltage arc tracking rate test 111 hinges 320 holding injection pressure phase 276 hold pressure 27, 30, 188, 199, 202, 207, 209, 375 hold pressure stage 27, 203, 321 hold pressure switching 188 hold pressure time 29, 189, 353 hold pressure time with sealed gate 355 holes and craters 338 homodisperse 7 homogeneous melt 186 homogeneous thicknesses 243 homopolymer 11 homopolymer POM 50 horizontal HB test 98 hot-air ovens 345 hot ball pressure test 96 hot runner 222, 307 hot runner nozzle 254 hot wire ignition HWI 139 hot wire ignition test 110 hydraulic piston clamping system 163 hydrocarbons 5

hydrolysis 37, 38 hydrolysis stabilizers 81 hydrolyzed parts 37 hydrophilic polymers 38 hydrophobic polymers 38 hygroscopic materials 331

П

identification of plastics 36 impact modifiers 82 impact resistance 119, 246 incandescent glow wire test 100 increasing surface tension 260 injection and cavity pressures 205 injection graphs 365 injection molding machine 161 injection peak pressure 275 injection pressure 187, 194, 209 injection pressure at switching point 202 injection pressure evolution 203 injection pressure limit 274, 276, 353 injection pressure losses 280 injection process 263 injection speed 178, 198, 207 injection speed linearization study injection speed machine performance 269 injection speed profile 335, 353 injection speed units conversion 289 injection stage 26 injection unit 161 in-mold rheology 288, 289 inner ring gate 235 input and output water lines 359 inputs and outputs 282 insufficient filling 355 intensification ratio 266 internal and external undercuts 246 internal micropores 365 internal stresses 343 internal voids 347 intumescence 78

ionomer 63

ISO 5271-2 88

isochronous lines 178 isocyanate 374 isotactic 12 Izod test 92

J

jetting 320, 334

K

ketones 68 key parameters 204

L

lack of adhesion 341 lack of crystallinity 324 lack of ventilation 364 lamellae 33 land channel 364 L/D ratio 167 length or land of the gate 319 light stabilizers 75 limited oxygen index (LOI) 142 linear 11 linear low density polyethylene (LLDPE) 47 liquid crystal polymer (LCP) 59 LLDPE 47 LOI test 99 low density polyethylene 46 lubricants 75

M

machine injection speed performance study 289
machine nozzle 369
machine portability 282, 289
masterbatch 85
material degradation 372
materials drying 316
material selection 134
material viscosity 208
matte surface 363
maximum available pressure 281
maximum peripheral screw speed 194

maximum recommended moisture polyester polyol 62 346 polyether polyol 62 open nozzle 172 maximum shear friction recompolyethersulfone (PESU) 64 optical brighteners 86 mended 285 polyethylene 23 optimum injection speed range 269 Maxwell-Voigt model 19 polyethylene terephthalate (PET) 56 optimum time for holding pressure polymerization 3 mechanical toggle clamping system 279 polymers 3 orientation 344 medium or high impact PS (HIPS) polymethylmethacrylate (PMMA) 58 oriented material layers 337 52 polyol 374 outer ring gate 235 melt flow index 116 polyolefins 46 overdrying 327 melt flow rate (MFR) test 104 polyoxymethylene (POM) 50 overlarged jump gate 236 melting temperature 16, 94 polyphenylene oxide (PPO) 57 melt temperature 184, 206, 322 polyphenylene sulfide (PPS) 63 melt temperature measurement 322 polyphenyl sulfone (PPSU) 64 melt temperature recommendations polypropylene (PP) 49 painting 339 209 polystyrenes (PS) 51 parameters deviations 192 polysulfone (PSU) 65 melt volume index 115 part dimensions 199 metal or plastic inserts 320 polyurethane (TPU) 61 parting lines 303 MFI 355 POM 357 part molded with stress 339 microbubbles 350 POM foaming test 257 part requirements checklist 129 microcraters 357 POM homopolymer 31, 257 part temperature 207 microstreaks 380 portability 282 part weight control 279 mineral additives 83 portability spreadsheet 283 PC-ABS 355 mineral fillers 83 post-shrinkage 324 peaks 343 moisture 37 PP copolymers 49 percentages of pressure loss 280 mold care 326 precious runners 279 peripheral screw speed units conmold cooling 226 preliminary investigation of failures version 289 mold deposits, types of 325 309 peripheral speeds 387 mold design 182 pressure drops 280 pheripheric screw speed recommenmold design guide 218 pressure evolution 187 dations 209 molding processor 264 pressure-limited process 274, 280, pin gate 236 mold surface temperature 323 365 pin point gate 232 mold temperature 190, 191, 206, 383 pressure multiplier 176 plasma 341 mold temperature recommendations pressurized water 325 plasticization 37, 38 209 previous calculations 194 plasticizers 76 mold temperatures setting 196 process optimization 310 plasticizing capacity 167 molecular orientation 335 process outputs 265, 282 plastics 3 molecular weight 7, 371 process start-up 193 plastic parts design 239 monomers 3 process validation 282 platens 303 multiple machine drying system 289 process window 267, 276, 277 plating process 343 process window study 289 **PMMA 361** progressive filling 280 Ν polar moment of inertia 240 progressive mold filling 202 polyacetals 23 Newtonian area 272 progressive mold filling setting 201 polyamides (PA) 54

polybutylene terephthalate (PBT) 56

polycarbonate 58, 356, 367

polydispersity 7

polyester 56, 316

proper crystallization 324

properly dehumidifying 317

ture 324

properly adjusting the mold tempera-

nitrided screw 169

nozzle 171, 304

notches, influence 245

nozzle diameter 252, 366

nucleating agents 81

purging or cleaning 255 sector regulations checklist 130 streaks caused by moisture 330 PVT graphs 25 streaks caused by trapped air 331 semi-crystalline 9 semi-spherical facilitator 351 stress 88 servoelectric clamping 164 stress concentrators 245, 346 R sharp corners 244, 334, 337, 357 stress cracking 110, 338, 349 radiation 107 sharp edges 349 styrene acrylonitrile (SAN) 53 radii 310, 349 shear 337 styrene butadiene copolymer (SBC) ratio dosage/screw 175 shear calculation 286 62 reaction to fire 101 shear rate 14, 285 submarine or tunnel gate 232 refraction of light 334 shear stress at the gates 284 subrunner 250 refractive index 108 shear stresses 280 substrate 339 refrigeration system 304 Shore A 91 suction 198, 368 regrind, amount 330 Shore D 91 surface orientation 183 relative temperature index, RTI 125 short hold pressure times 321 surface resistivity 124, 135 relative temperature index test 112 short parts 277 surface resistivity test 103 relative viscosity method 267 shrinkage 209, 230, 279, 384 surface scratching 338 relaxation 20, 248 silica 305 surface tension 258, 341 residence time 335, 383 switching point 202, 278, 353 silver marks 337, 369 residence time of material 175, 195 silver streaks 330, 331 switching point to holding pressure residence time recommendations sinkings 340 209 sink marks 277, 320, 328 switching pressure 200 residual stress 108, 339 slips additive 81 switching to hold pressure stage resin handling 307 slots and undercuts 246 reverse taper nozzle 172 small gates 318 syndiotactic 12 rheology 13 small holes 338 systematic progressive 272 rheometer 115 snap-fit 247 ribs and reinforcements designs solvent 339 Ť 239 specific injection pressure 177 ribs design 240 Taber test 90 specific units 282 rigidity 248 tab gate 233 specific volume 25, 26 RTI test 96 tangential screw speed 185 speed profile 180 runners 318, 374 tangential speed 186 spherical nozzle 172 runners and gates systems 250 taper nozzle 172 spherulites 34 runners and sprue 370 target factor values checklist 131 spiral effect 253, 284, 353 runners design 220, 221 technical specifications checklist splay 337, 369 runners ejectors 364 130 spots 343 Teflon 23 spots and markings near the gate temperature 196 335 S tensile modulus 118 sprue diameter 252 saving material solutions 241 tensile stresses 241 sprue diameter, small 250, 319 scientific method 264 tensile test 88, 118 stabilizers 74 scientific molding 263 start-up and fine-tuning of injection theoretical clamping force estimation scratch resistance test 93 289 machines 201 screw 167, 303 steel selection 219 thermal conductivity 123 screw holes 249 thermodynamics 25 steps for analysis 311 screw mechanism 169 thermographic analysis 359 strain 88 screw non-return valve hermeticity thermoplastic copolymer elastomer strain at break 118 study 289 ether ester (TPC ET) 60 streaks 315, 330, 357, 367

screw peripheral speed 185

thermoplastic elastomer (TPE-V) 59

thermoplastics 8 thermoregulators 307 thermostable 10 thickness, changes 243 thickness design 242 thickness of ribs 239 thickness problems 242 thick to thin 320 thick to thin rule 351 time-dependent process 279 time of arc resistance test 111 titanium nitride 326 toggle kinematics 197 torsion resistance 240 TPC-ET 345 TPU 373 transparent polymers 156 trapped air 338, 377 traverse optimal temperature test trials injection molding parameters template 314 troubleshooter questions 311 tubular frames 249 tubular parts 320 turbulent flow 304, 359 typical problems in plastics injection 315

U

UL94 97
UL temperature See relative temperature index RTI
unbalanced runners 220, 252, 372
uncompensated shrinkage 377
unfilled part 351
universal process data sheet 289
UV protection 76

٧

vacuoles 318, 329, 346 vacuum problems 375 vaporization 38 venting 227, 255 venting channels 386 venting depth for amorphous plastics 228 venting depth for semi-crystalline plastics 227 venting depth recommendation 256 venting for runners 228 venting in ejectors 229 venting length 256 venting recommendations 209 Vicat softening temperature 121 Vicat test 95

viscosity 13, 269 viscosity curve 273 volume resistivity test 104 volume shrinkage 321 vulcanization 22

W

warpage 338
warping 320, 360
water influences 37
water in polyamides 37
weathering test 105
weight at switch point 266
weld lines 183, 190, 332, 350, 356
white streaks 331

Υ

yield point 118 yield stress 117