

HANSER

Runner and Gating Design Handbook

John Philip Beaumont

Tools for Successful Injection Molding

ISBN 3-446-22672-9

Weitere Informationen oder Bestellungen unter
<http://www.hanser.de/3-446-22672-9> sowie im Buchhandel

Contents

1	Overview of Runners, Gates, and Gate Positioning	1
1.1	Primary Parting Plane Runners	1
1.2	Sub Runners	2
1.2.1	Cold Sub Runners	2
1.2.2	Hot Sub Runners	2
1.3	Hybrid Sub-Runner and Parting Line Runner	3
1.4	Gate Designs	3
2	Rheology of Plastics	5
2.1	Laminar vs. Turbulent Flow	5
2.2	Fountain Flow	6
2.3	Factors Affecting Viscosity	7
2.3.1	Common Viscosity Models	7
2.3.2	Non-Newtonian Fluids	9
2.3.3	Temperature	10
2.3.4	Pressure	10
2.4	Melt Compressibility	11
2.5	Melt Flow Characterization	11
3	Filling and Packing Effects on Material and Molded Part	15
3.1	Process Effects on Material Viscosity	15
3.1.1	Melt Thermal Balance – Conductive Heat Loss vs. Shear Heating	15
3.1.2	Development of a Frozen Boundary Layer	17
3.2	Factors Affecting Plastic Material Degradation	18
3.2.1	Excessive Shear	18
3.2.2	Excessive Temperature	20
3.3	Effects of Mold Fill Rate on Fill Pressure	21
3.4	Post Filling or Packing Phase	22
3.4.1	Thermal Shrinkage as Plastic Cools	22
3.4.2	Compensation Flow to Offset Volumetric Shrinkage	23
3.4.3	Pressure Distribution During the Post Filling Phase	23
3.4.4	Gate Freeze-Off	24
3.5	Melt Flow Effects on Material and Molded Parts	25
3.5.1	Shrinkage	25
3.5.1.1	Volumetric Shrinkage	25
3.5.1.2	Orientation-Induced Shrinkage	27

3.5.2	Development of Residual Stresses and Warpage	30
3.5.2.1	Warpage and Residual Stress from Side-to-Side Shrinkage Variations . .	31
3.5.2.2	Warpage and Residual Stress from Global/Regional Shrinkage Variations	31
3.5.2.3	Warpage and Residual Stress from Orientation-Induced Shrinkage Variations.	32
3.5.3	Physical Properties as Effected by Orientation	32
3.6	Annealing a Molded Part	33
3.7	Summary	33
4	Gate Positioning and Molding Strategies	37
4.1	Gate Positioning Considerations	37
4.2	Design and Process Strategies for Injection Molding	39
4.2.1	Maintain Uniform Wall Thicknesses in a Part	39
4.2.2	Use Common Design Guidelines for Injection Molded Plastic Parts with Caution	40
4.2.3	Avoid Flowing from Thin to Thick	41
4.2.4	Establish a Simple Strategic Flow Pattern within a Cavity	42
4.2.5	Avoid Picture Framing	44
4.2.6	Integral Hinges	45
4.2.7	Balanced Filling Throughout a Mold	48
4.2.7.1	Gating Position(s) Within a Cavity	48
4.2.7.2	Multi-Cavity Molds	51
4.2.8	Provide for Uniform Temperatures (Mold and Melt)	53
4.2.9	Eliminate, Strategically Place, or Condition Welds	54
4.2.10	Avoiding Flow Hesitation	55
4.2.11	Managing Frictional Heating of the Melt	56
4.2.12	Minimize Runner Volume in Cold Runners	57
4.2.13	Avoid Excessive Shear Rates	58
4.2.14	Avoid Excessive, and Provide for Uniform, Shear Stresses	60
5	The Melt Delivery System	63
5.1	Runner Design Fundamentals	63
5.2	Overview of Runner/Melt Delivery System	64
5.2.1	Machine Nozzle	65
5.2.1.1	Nozzle Filter	66
5.2.1.2	Static Mixers	66
5.2.2	Sprue	66
5.2.3	Runner	67
5.2.4	Gate	67
5.3	Melt Flow Through the Melt Delivery System	67

5.3.1	Melt Preparation – The Injection Molding Machine	67
5.3.1.1	Pressure Development from a Molding Machine	68
5.3.1.2	Flow Through a Runner Channel	69
5.3.2	Effect of Temperature on Flow	70
5.3.2.1	Melt Temperature	70
5.3.2.2	Mold Temperature	71
5.3.3	Cold vs. Hot Runners	71
5.3.4	Pressure Drop through the Melt Delivery System (Nozzle vs. Sprue vs. Runner vs. Gate vs. Part Forming Cavity)	72
5.4	Use of Mold Filling Analysis	73
5.5	Runner Cross Sectional Size and Shape	74
5.5.1	The Efficient Flow Channel	74
5.5.2	Pressure Development in the Runner	75
5.5.2.1	Flow through a Hot Runner vs. a Cold Runner	77
5.5.3	Runner Effect on Cycle Time	78
5.5.3.1	Cold Runner and Sprue Cooling Time	78
5.5.3.2	Hot Runner	78
5.5.4	Constant Diameter vs. Varying Diameter Runners	78
5.6	Designing Runners for Shear- and Thermally-Sensitive Materials	80
5.7	Runner Layouts	81
5.7.1	Geometrical Balanced Runners	82
5.7.2	Non-Geometrically Balanced Runners	82
5.7.3	Family Molds	83
6	Filling and Melt Imbalances Developed in Multi-Cavity Molds	85
6.1	Source of Mold Filling Imbalances	85
6.1.1	Imbalances Developed from the Runner	85
6.1.2	Imbalance Caused by Non-Runner Layout Issues	87
6.2	Imbalance Effects on Process, Product, and Productivity	90
6.3	Shear-Induced Melt/Molding Imbalances in Geometrically Balanced Runners	94
6.3.1	Development and Stratification of Melt Variations Across a Runner Channel ...	94
6.3.2	Laminate Separation in Branching Runners Causing Cavity-to-Cavity Filling Imbalances	95
6.3.3	Shear Induced Melt Imbalances in Stack Molds	97
6.3.4	Development of Intra-Cavity Variations	98
6.3.4.1	Warpage	99
6.3.4.2	Core Deflection	99
6.3.4.3	Effect on Concentric Parts (Gears, Fans, and Others)	100
6.3.5	Alternative Theories of the Cause of Mold Filling Imbalances	101

6.3.5.1	Cooling Variations	101
6.3.5.2	Plate Deflection	101
6.3.5.3	Corner Effect	102
6.3.5.4	Melt Pressure as the Cause of Filling Imbalance	102
6.4	Runner Layouts	103
6.4.1	Identification of Various Flow Groups in Common Geometrically Balanced Runners	103
6.4.2	Apparent Geometrically Balanced Runner Layouts	104
6.5	Effect of Shear-Induced Melt Variations on Two-Stage Injection Processes	105
6.5.1	Gas Assist Injection Molding	105
6.5.2	Co-Injection Molding	106
6.5.3	Structural and Microcellular Foam Molding	107
6.6	The Cost of Melt Imbalances	108
7	Managing Shear-Induced Melt Variations for Successful Molding	111
7.1	Static Mixers	111
7.2	Artificially Balancing	113
7.2.1	Varying Sizes of Branching Runners or Gates to Achieve a Filling Balance	113
7.2.2	Varying Temperatures to Control Filling Balance	114
7.3	Melt Rotation Technology	114
7.3.1	Melt Rotation Technology in Hot Runner Molds	119
7.3.2	Melt Rotation Technology in Cold Runner Molds	120
7.3.3	Melt Rotation for Intra-Cavity Imbalances	121
7.3.4	Multi-Axis Melt Symmetry	122
7.4	Melt Rotation for Controlling Two Stage Injection Processes	124
8	Cold Runner Molds	127
8.1	Sprue	128
8.1.1	Cold Sprue	128
8.1.2	Hot Sprue	131
8.2	The Cold Runner	131
8.2.1	Important Machining Considerations	133
8.2.2	Sizing of Runners	134
8.2.3	Venting	135
8.2.4	Runner Ejection	135
8.2.4.1	Sprue Puller	135
8.2.4.2	Secondary Sprue/Cold Drop	136
8.2.4.3	Runner	137
8.2.5	Cold Slug Wells	137

8.3	Runners for Three-Plate Cold Runner Molds	138
8.4	Gate Designs	140
8.4.1	Sprue Gate	141
8.4.2	Common Edge Gate	142
8.4.3	Fan Gate	143
8.4.4	Film Gate or Flash Gate	144
8.4.5	Ring Gate	144
8.4.6	Diaphragm Gate	145
8.4.7	Tunnel Gate	146
8.4.8	Cashew or Banana Gate	147
8.4.9	Jump Gate	148
8.4.10	Pin Point Gate	148
8.4.11	Chisel Gate	148
8.4.12	Tab Gate	149
9	Hot Runner Molds	151
9.1	Overview	151
9.1.1	Advantages and Disadvantage of Hot Runner Systems	152
9.1.1.1	Advantages of Hot Runners	152
9.1.1.2	Disadvantages of Hot Runners	154
9.1.1.3	Summary of Attributes of Different Runner Systems	156
9.2	Overview of Multi-Cavity Hot Runner Systems (Contrasting Systems)	157
9.2.1	Externally Heated Manifold and Drops/Nozzles	158
9.2.2	Externally Heated Manifold with Internally Heated Drops	159
9.2.3	Internally Heated Manifold and Internally Heated Drops	160
9.2.4	Insulated Manifold and Drops	160
9.3	Stack Molds	161
10	Hot Runner Flow Channel Design	163
10.1	Layout for Balanced Molding	163
10.2	Cross-Sectional Shape	164
10.3	Corners	165
10.4	Effect of Diameter	166
10.4.1	Pressure	166
10.4.2	Shot Control	168
10.4.3	Color Change	169
10.4.4	Material Change	172

11 Hot Runner Drops, Nozzles and Gates	173
11.1 Hot Drops	174
11.1.1 Externally Heated Hot Drops (Nozzles)	174
11.1.2 Internally Heated Hot Drops	175
11.1.3 Heat Conducting Nozzles	175
11.2 Restrictive/Pin Point Gates	176
11.3 Gate Design Considerations	177
11.3.1 Gate Freeze-Off	177
11.3.2 Stringing/Drooling	178
11.3.3 Packing	178
11.3.4 Mechanical Valve Gates	180
11.3.4.1 Sequential Valve Gates	182
11.3.5 Thermal Shut-Off Gates	183
11.3.6 Hot Edge Gates	183
11.3.7 Multi Tip Nozzles	184
12 Thermal Issues of Hot Runner Systems	185
12.1 Heating	185
12.1.1 Coil (Cable) Heaters	186
12.1.2 Band Heaters	186
12.1.3 Tubular Heaters	187
12.1.4 Cartridge Heaters	187
12.1.5 Heat Pipe Technology	188
12.2 Heater Temperature Control	188
12.2.1 Thermocouples	188
12.2.2 Temperature Controllers	189
12.3 Power Requirements	190
12.4 Thermal Isolation of the Hot Runner	191
12.5 Gate Temperature Control	193
12.5.1 Gate Heating	194
12.5.2 Gate Cooling	194
13 The Mechanics and Operation of Hot Runners	195
13.1 Assembly and Leakage Issues	195
13.1.1 System Design	196
13.1.2 Hot Runner System Machining and Assembly	198
13.2 Mold and Machine Distortions	201
13.3 Startup Procedures	202
13.4 Color and Material Changes	203

13.5	Gates	204
13.5.1	Vestige	204
13.5.2	Clog	204
13.5.3	Wear	205
13.6	Maintenance	205
14	Process of Designing and Selecting a Runner System (Gate and Runner) – A Summary	207
14.1	Number of Gates	207
14.2	Gating Position on a Part	207
14.2.1	Cosmetic	207
14.2.2	Effect on Shrinkage, Warp, and Residual Stress	208
14.2.2.1	Orientation	208
14.2.2.2	Volumetric Shrinkage (Regional)	208
14.2.2.3	Unbalanced Filling	209
14.2.3	Structural Issues	209
14.2.3.1	Gate Stress	209
14.2.3.2	Flow Orientation	210
14.2.4	Gating into Restricted, or otherwise Difficult to Reach Locations	210
14.3	Cavity Positioning	210
14.4	Material	210
14.5	Jetting	211
14.6	Thick vs. Thin Regions of the Part	211
14.6.1	Volumetric Shrinkage	211
14.6.2	Hesitation	211
14.7	Number of Cavities	211
14.8	Production Volume	212
14.9	Precision Molding (Precision Size, Shape, Weight, Mechanical Properties and Consistency)	212
14.10	Color Changes	212
14.11	Material Change	213
14.12	Regrind of Runners	213
14.13	Part Thickness	213
14.13.1	Thin Part	213
14.13.2	Thick Part	214
14.14	Part Size	214
14.15	Labor Skill Level	214
14.16	Post Mold Handling	215
14.17	Part/Gate Stress Issues	215
14.18	Hot and Cold Runner Combinations	215
14.19	Two-Phase Injection Processes	215

15 Troubleshooting	217
15.1 The 5 Step Process™	217
15.1.1 Shear-Induced Flow Imbalance Developed in a Geometrically Balanced Runner ..	217
15.1.2 Steel Variations in the Mold	218
15.1.3 Cooling Affects	218
15.1.4 Hot Runner Systems	219
15.1.5 Summary of Test Data	219
15.1.6 The 5 Step Process: Method of Application	219
15.2 Injection Molding Troubleshooting Guidelines for Scientific Injection Molding	221
15.3 Two Stage Molding Set-Up	268
15.4 Intensification Ratio (Ri)	279
15.5 Characterizing Flow Behavior in an Injection Mold	280
15.6 List of Amorphous and Semi-Crystalline Resins	280